Table of Contents

Dedication iii
Preface xvii

Chapter 1: Introduction to NX 10.0

Introduction to NX 10.0 1-2
System Requirements 1-4
Getting Started with NX Enhanced 1-4
Important Terms and Definitions 1-6
Understanding the Functions of the Mouse Buttons 1-10
Quick Access Toolbar Enhanced 1-11
Ribbon 1-12
Status Bar 1-16
Hot Keys 1-16
Color Scheme 1-17
Dialog Boxes in NX 1-17
Selecting Objects 1-18
Deselecting Objects 1-18
Selecting Objects Using the QuickPick Dialog Box 1-19
Self-Evaluation Test 1-19

Chapter 2: Drawing Sketches for Solid Models

Introduction 2-2
Starting NX Enhanced 2-3
Starting a New Document in NX 2-4
Invoking Different NX Environments 2-6
Creating Three Fixed Datum Planes (XC-YC, YC-ZC, XC-ZC) 2-7
Displaying the WCS (Work Coordinate System) 2-8
Creating Sketches 2-8
    Creating Sketches in the Modeling Environment 2-8
    Creating Sketches in the Sketching Environment 2-14
Sketching Tools 2-14
    Drawing Sketches Using the Profile Tool 2-14
    Using Help Lines to Locate Points 2-17
    Drawing Individual Lines 2-18
    Drawing Arcs 2-18
    Drawing Circles 2-20
    Drawing Rectangles 2-21
    Placing Points 2-23
    Drawing Ellipses or Elliptical Arcs 2-26

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Drawing Conics 2-28
Drawing Studio Splines 2-29
Filleting Sketched Entities 2-31
The Drawing Display Tools 2-33
Fitting Entities in the Current Display 2-33
Zooming an Area 2-33
Dynamic Zooming 2-34
Panning Drawings 2-34
Fitting View to Selection 2-34
Restoring the Original Orientation of the Sketching Plane 2-34
Setting Selection Filters in the Sketch in Task Environment 2-34
Selecting Objects 2-36
Deselecting Objects 2-36
Using Snap Points Options While Sketching 2-36
Deleting Sketched Entities 2-37
Exiting the Sketch Environment 2-37
Tutorial 1 2-38
Tutorial 2 2-42
Tutorial 3 2-47
Self-Evaluation Test 2-50
Review Questions 2-51
Exercise 1 2-52
Exercise 2 2-53

Chapter 3: Adding Geometric and Dimensional Constraints to Sketches

Constraining Sketches 3-2
Concept of Constrained Sketches 3-2
Under-Constrain 3-2
Fully-Constrain 3-2
Over-Constrain 3-2
Degree of Freedom Arrows 3-3
Dimensioning Sketches 3-4
Locking the Automatically Applied Dimensions 3-4
Applying Dimensions by Using the Rapid Dimension Tool 3-5
Applying Linear Dimensions 3-5
Applying Radial Dimensions 3-8
Applying Angular Dimensions 3-8
Applying Perimeter Dimensions 3-9
Editing the Dimension Value and Other Parameters 3-9
Animating a Fully-Constrained Sketch 3-9
Measuring the Distance Value between Objects in a Sketch 3-10
Measuring the Distance between Two Objects in a Sketch 3-11
Measuring the Projected Distance between Two Objects 3-11
Measuring the Screen Distance between Two Objects 3-12
Measuring the Length of an Arc or a Line 3-12
Measuring the Angle between Entities 3-13

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Measuring the Angle Value Using the By Objects Option 3-13
Measuring the Angle Value Using the By 3 Points Option 3-14
Measuring the Angle Value Using the By Screen Points Option 3-14
Geometric Constraints 3-15
Applying Additional Constraints Individually 3-15
Applying Symmetry Constraint 3-20
Applying Automatic Constraints to a Sketch 3-20
Controlling Inferred Constraints Settings 3-22
Showing All Constraints in a Sketch 3-22
Showing/Removing Constraints 3-22
Converting a Sketch Entity or Dimension into a Reference Entity or Reference Dimension 3-24
Tutorial 1 3-25
Tutorial 2 3-30
Tutorial 3 3-33
Self-Evaluation Test 3-35
Review Questions 3-36
Exercise 1 3-37
Exercise 2 3-38

Chapter 4: Editing, Extruding, and Revolving Sketches

Editing Sketches 4-2
Trimming Sketched Entities 4-2
Extending Sketched Entities 4-3
Creating a Corner between Sketched Entities 4-4
Moving Sketched Entities by Using the Move Curve Tool 4-5
Offsetting Sketched Entities by Using Offset Move Curve 4-10
Modifying Entities by Using the Resize Curve Tool 4-11
Modifying Chamfer in Sketched Entities by Using Resize Chamfer Curve Tool New 4-13
Deleting Sketched Entities by Using Delete Curve Tool 4-13
Offsetting Sketched Entities 4-14
Mirroring Sketched Entities 4-16
Creating a Linear Sketch Pattern 4-17
Creating a Circular Sketch Pattern 4-18
Creating a General Sketch Pattern 4-19
Transforming Sketched Entities 4-19
Editing Sketched Entities by Dragging 4-22
Exiting the Sketch Environment 4-23
Changing the View of the Sketch 4-23
Creating Base Features by Extruding 4-24
Extrude Dialog Box Options 4-24
Creating Solid Revolved Bodies 4-31
Copying, Moving, and Rotating Objects 4-35
Hiding Entities 4-40
Showing Hidden Entities 4-40
Hiding All Entities Using a Single Tool 4-40
Rotating the View of a Model in 3D Space 4-41

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Setting Display Modes 4-42
Tutorial 1 4-42
Tutorial 2 4-44
Tutorial 3 4-48
Self-Evaluation Test 4-51
Review Questions 4-51
Exercise 1 4-52
Exercise 2 4-53

Chapter 5: Working with Datum Planes, Coordinate Systems, and Datum Axes

Additional Sketching and Reference Planes 5-2
Types of Datum Planes 5-3
    Creating Three Fixed (Principle) Datum Planes 5-3
    Creating Relative Datum Planes 5-3
Creating Datum Coordinate Systems 5-9
Creating Fixed and Relative Datum Axes 5-13
Other Extrusion Options 5-16
    Specifying the Boolean Operation 5-16
    Specifying Other Extrusion Termination Options 5-18
Projecting External Elements 5-20
Tutorial 1 5-22
Tutorial 2 5-26
Tutorial 3 5-30
Self-Evaluation Test 5-34
Review Questions 5-35
Exercise 1 5-36
Exercise 2 5-37
Exercise 3 5-38

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools 6-2
Creating Holes by Using the Hole Tool 6-2
    Creating General Holes 6-2
    Creating Drill Size Hole 6-4
    Creating Screw Clearance Hole 6-5
    Creating Threaded Hole 6-5
    Creating Hole Series 6-6
Creating Grooves 6-6
    Creating Rectangular Grooves 6-7
    Creating Ball End Grooves 6-8
    Creating U Grooves 6-9
Creating Slots 6-11
    Creating Rectangular Slots 6-11
    Creating Ball-End Slots 6-13
    Creating U-Slots 6-15
    Creating T-Slots 6-16

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Dove-Tail Slots 6-18
Creating Ribs 6-19
Creating Chamfers 6-22
Creating a Chamfer Feature Using the Symmetric Method 6-22
Creating a Chamfer Feature Using the Asymmetric Method 6-23
Creating a Chamfer Feature Using the Offset and Angle Method 6-24
Creating an Edge Blend 6-25
Tutorial 1 6-31
Tutorial 2 6-37
Self-Evaluation Test 6-44
Review Questions 6-45
Exercise 1 6-46
Exercise 2 6-47
Exercise 3 6-48

Chapter 7: Advanced Modeling Tools-II

Advanced Modeling Tools 7-2
Pattern Feature Tool 7-2
Creating a Linear Pattern 7-2
Creating a Circular Pattern 7-7
Creating a Polygon Pattern 7-10
Creating a Spiral Pattern 7-11
Creating a Pattern Along a Curve 7-12
Creating a General Pattern 7-14
Creating a Reference Pattern 7-14
Creating a Helix Pattern 7-15
Creating a Fill Pattern 7-17
Mirror Feature Tool 7-19
Mirror Face Tool 7-20
Mirror Geometry Tool 7-21
Sweeping Sketches Along the Guide Curves 7-21
Creating Swept Features 7-23
Creating Tubes or Cables 7-25
Creating Threads 7-27
Creating Symbolic Threads 7-27
Creating Detailed Threads 7-29
Creating Shell Features 7-30
Shelling the Entire Solid Body 7-31
Tutorial 1 7-32
Tutorial 2 7-35
Tutorial 3 7-38
Tutorial 4 7-42
Self-Evaluation Test 7-48
Review Questions 7-49
Exercise 1 7-50
Exercise 2 7-50

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Chapter 8: Editing Features and Advanced Modeling Tools-III

Editing Features 8-2
Editing a Hole Feature 8-2
Editing the Positioning of a Groove Feature 8-2
Editing the Positioning of a Slot Feature 8-3
Editing the Parameters of Features 8-3
Editing the Parameters of Features with Rollback 8-3
Editing Sketches of the Sketch-based Features 8-3
Reordering Features 8-4
Advanced Modeling Tools 8-4
Creating Boss Features 8-4
Creating Pocket Features 8-5
Creating Pad Features 8-8
Creating Drafts 8-11
Tutorial 1 8-14
Tutorial 2 8-18
Tutorial 3 8-26
Self-Evaluation Test 8-33
Review Questions 8-34
Exercise 1 8-35
Exercise 2 8-36
Exercise 3 8-36

Chapter 9: Assembly Modeling-I

The Assembly Environment 9-2
Invoking the Assembly Environment 9-2
Invoking the Assembly Environment Using the New Dialog Box 9-2
Invoking the Assembly Environment in the Current Part File 9-2
Types of Assembly Design Approaches 9-3
Creating Bottom-up Assemblies 9-4
Placing Components in the Assembly Environment 9-4
Changing the Reference Set of a Component 9-6
Applying Assembly Constraints to Components 9-7
Points to Remember while Assembling Components 9-16
Creating a Pattern Component in an Assembly 9-17
Replacing a Component in an Assembly 9-19
Moving a Component in an Assembly 9-20
Mirroring a Component in an Assembly 9-24
Modifying a Component in the Assembly File 9-26
Tutorial 1 9-27
Tutorial 2 9-40
Self-Evaluation Test 9-52
Review Questions 9-53
Exercise 1 9-54

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Exercise 2 9-56
Exercise 3 9-59
Exercise 4 9-62

Chapter 10: Assembly Modeling-II

The Top-down Assembly Design Approach 10-2
Creating Components Using the Top-down Assembly Design Approach 10-2
Creating Subassemblies 10-4
Editing Assembly Constraints 10-5
Checking the Interference between the Components of an Assembly 10-6
Checking Interference Using the Simple Interference Tool 10-6
Checking Interference Between the Assembly Components 10-7
Checking Interference and Clearance, and Analyzing Cross-sections of Components Using the View Section Tool 10-11
Creating Exploded Views of an Assembly 10-16
Exploding Views Automatically 10-17
Exploding Views Manually 10-19
Tutorial 1 10-20
Tutorial 2 10-24
Tutorial 3 10-29
Tutorial 4 10-35
Self-Evaluation Test 10-40
Review Questions 10-40
Exercise 1 10-41
Exercise 2 10-46
Exercise 3 10-53

Chapter 11: Surface Modeling

Introduction to Surface Modeling 11-2
Invoking the Shape Studio Environment 11-2
Creating an Extruded Surface 11-2
Creating a Revolved Surface 11-3
Creating a Ruled Surface 11-4
Creating a Surface Using the Through Curves Tool 11-6
Creating a Surface Using the Through Curve Mesh Tool 11-7
Creating a Surface Using the Four Point Surface Tool 11-9
Creating a Swoop Surface 11-10
Creating Planar Surfaces from 2D Sketches and Edges of Solid or Surface 11-11
Creating a Transition Surface Using the Transition Tool 11-12
Creating an N-Sided Surface 11-14
Creating a Silhouette Flange Surface 11-17
Extending a Surface Using the Law Extension Tool 11-21
Creating a Surface Offset Using the Offset Surface Tool 11-24
Trimming and Extending a Surface Using the Trim and Extend Tool Enhanced 11-25
Trimming a Sheet by Using the Trimmed Sheet Tool 11-26
Creating a Surface Using the Studio Surface Tool 11-28
Creating a Surface between Two Walls Using the Styled Blend Tool 11-31

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Creating Surfaces Using the Styled Sweep Tool 11-35
Sewing Individual Surfaces into a Single Surface 11-37
Adding Thickness to a Surface 11-37
Adding a Draft 11-38
Tutorial 1 11-40
Tutorial 2 11-45
Self-Evaluation Test 11-53
Review Questions 11-54
Exercise 1 11-55
Exercise 2 11-56

Chapter 12: Advanced Surface Modeling

Creating Curves from Bodies 12-2
Creating Intersection Curves 12-2
Creating Section Curves 12-3
Creating Extract Curves 12-8
Creating Isoparametric Curves 12-9
Projecting Curves 12-11
Advanced Surface Modeling Tools 12-14
Creating Dart Features 12-14
Creating Emboss Body on a Sheet or Solid Body 12-16
Creating Face Blend Features Enhanced 12-17
Creating Bridge Features 12-23
Tutorial 1 12-25
Tutorial 2 12-35
Tutorial 3 12-44
Self-Evaluation Test 12-55
Review Questions 12-56
Exercise 1 12-56
Exercise 2 12-57

Chapter 13: Generating, Editing, and Dimensioning the Drawing Views

The Drafting Environment 13-2
Invoking the Drafting Environment 13-2
Invoking the Drafting Environment Using the Drawing Template from the New Dialog Box 13-2
Invoking the Drafting Environment in the Current Part File 13-3
Editing the Drawing Sheet Parameters in the Drafting Environment 13-6
Invoking the Drafting Tools 13-6
Types of Drawing Views in NX 13-6
Base View 13-6
Projected View 13-6
Detail View 13-6
Section View 13-6
Auxiliary View 13-7
Half-Section View 13-7
Revolved Section View 13-7

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Break-Out Section View 13-7
Broken View 13-7
Generating Drawing Views 13-7
Generating Views Using the View Creation Wizard Tool 13-7
Generating the Base View 13-12
Generating the Orthographic Drawing Views Using the Projected View Tool 13-14
Generating the Detail View Using the Detail View Tool 13-15
Creating a Section Line New 13-18
Generating Section Views Using the Section View Tool Enhanced 13-20
Generating the Break-Out Section View 13-25
Generating the Broken View 13-26
Manipulating the Drawing Views 13-28
Moving the Drawing Views Using the Move/Copy View Tool 13-28
Aligning the Drawing Views Using the Align View Tool 13-29
View Boundary 13-31
Section in View Tool 13-32
Displaying the Model Using the Display Sheet Tool 13-33
Inserting a Drawing Sheet Using the New Sheet Tool 13-34
Modifying the Properties of the Generated Drawing View 13-34
Modifying the Scale Value of the Drawing View 13-34
Adding Dimensions to the Drawing Views 13-36
Retrieving Dimensions from the Model 13-36
Adding Dimensions to the Drawing View 13-37
Generating Exploded Views of an Assembly 13-41
Creating Parts List and Associative Balloons 13-41
Creating a Parts List for an Assembly 13-42
Creating Associative Balloons 13-42
Creating a Tabular Note (Title Block) 13-43
Adding Multiline Text to a Drawing Sheet 13-45
Printing Tools 13-46
Print 13-46
Plot 13-46
Tutorial 1 13-47
Tutorial 2 13-52
Tutorial 3 13-58
Self-Evaluation Test 13-65
Review Questions 13-66
Exercise 1 13-67
Exercise 2 13-67

Chapter 14: Synchronous Modeling

Introduction 14-2
Move Face 14-2
Move Edge 14-5
Pull Face 14-7
Offset Region 14-8

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Offset Edge 14-9
Replace Face 14-10
Resize Blend 14-11
Reorder Blends 14-12
Resize Chamfer 14-13
Label Chamfer 14-14
Label Notch Blend 14-14
Resize Face 14-14
Delete Face 14-15
Copy Face 14-17
Cut Face 14-18
Paste Face 14-19
Mirror Face 14-20
Pattern Face 14-20
Make Coplanar 14-21
Make Coaxial 14-22
Make Tangent 14-23
Make Symmetric 14-24
Make Parallel 14-25
Make Perpendicular 14-26
Make Fixed 14-27
Make Offset 14-28
Show Related Face 14-29
Linear Dimension 14-30
Angular Dimension 14-31
Radial Dimension 14-33
Shell Body 14-34
Shell Face 14-35
Change Shell Thickness 14-36
Group Face 14-37
Edit Cross Section in History Free Mode 14-38
Edit Cross Section in History Mode 14-39
Tutorial 1 14-40
Tutorial 2 14-46
Self-Evaluation Test 14-55
Review Questions 14-56
Exercise 1 14-57
Exercise 2 14-57

Chapter 15: Sheet Metal Design

The Sheet Metal Module 15-2
Setting the Sheet Metal Part Properties 15-3
Creating the Base Feature 15-7
Adding Flanges to a Sheet Metal Part 15-8
Creating Contour Flanges 15-15
Creating Lofted Flanges 15-16
Adding a Jog to the Sheet 15-17

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com

Bending the Sheet Metal Part 15-18
Unbending the Sheet Metal Part 15-19
Rebending the Sheet Metal Part 15-19
Filleting or Chamfering Corners 15-19
Closing the Corners of a Sheet Metal Part 15-20
Creating Dimples in a Sheet Metal Part 15-23
Creating Louvers in a Sheet Metal Part 15-26
Creating Drawn Cutouts in a Sheet Metal Part 15-28
Creating Beads in a Sheet Metal Part 15-28
Adding Gussets to a Sheet Metal part 15-31
Adding Hems 15-34
Creating a Sheet Metal Part Using Solid Body 15-37
Converting a Solid Part into a Sheet Metal Part 15-38
Ripping the Corners of a Solid Part 15-39
Creating the Flat Pattern of a Sheet Metal Part 15-39
    Creating the Flat Pattern 15-40
    Creating the Flat Solid 15-40
    Exporting a Flat Pattern 15-41
Tutorial 1 15-41
Tutorial 2 15-52
Self-Evaluation Test 15-57
Review Questions 15-58
Exercise 1 15-58
Exercise 2 15-60

Student Projects **SP-1**
Index **I-1**

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com