

# Table of Contents

<b>Dedication</b>	iii
<b>Preface</b>	xiii

## **Chapter 1: Introduction to EdgeCAM**

EdgeCAM 10.0	1-2
EdgeCAM Part Modeler	1-2
Model Mode	1-2
Drawing Mode	1-2
Getting Started with the EdgeCAM Part Modeler	1-3
EdgeCAM	1-4
Design Mode	1-4
Manufacture Mode	1-4
Getting Started with EdgeCAM	1-4
System Requirements for EdgeCAM 10.0	1-5
Understanding Functions of the Mouse Buttons	1-5
Toolbars	1-6
EdgeCAM Part Modeler Toolbars	1-7
EdgeCAM Toolbars	1-9
Important Terms and Definitions	1-14
Entities	1-14
Digitise	1-15
Hot Keys	1-15
Color Scheme	1-15
Color Scheme in the EdgeCAM Part Modeler	1-16
Color Scheme in EdgeCAM	1-17
Self-Evaluation Test	1-18

## **Chapter 2: Drawing Sketches for Solid Models in the EdgeCAM Part Modeler**

The Sketching Environment	2-2
Starting a New File in the Part Modeler	2-2
Configuring the Document Options	2-4
Modifying the Dimensioning Units	2-4
Default value\Increment Area	2-5
Modifying the Snap and Grid Settings	2-5
Learning about Sketcher Terms	2-6
Origin	2-6
World Origin	2-6
Inferencing Lines	2-6

Select/Modify Tool	2-7
Locating a Position on a Sketch	2-7
Model Window	2-9
Object Selection Method	2-10
Selecting the Entities Using a Window	2-10
Selecting the Entities Using a Crossing	2-10
Drawing Sketches using the Sketcher Tools	2-10
Drawing Lines	2-10
Using the Second Level Modifier Toolbar	2-11
Drawing Arcs	2-12
Drawing Circles	2-14
Drawing Conics	2-15
Creating Basic Geometric Shapes	2-17
Drawing Splines	2-19
Placing a Point	2-21
2D Points on a Curve	2-21
Writing Text	2-21
Editing Sketched Entities	2-22
Offsetting the Curve	2-22
Filleting Sketched Entities	2-24
Chamfering Sketched Entities	2-25
Trimming Sketched Entities	2-27
Translating Sketched Entities	2-30
Rotating Sketched Entities	2-31
Mirroring Sketched Entities	2-32
Creating a Rectangular Array	2-33
Creating a Circular Array	2-33
Scaling Entities	2-34
Tutorial 1	2-35
Tutorial 2	2-40
Self-Evaluation Test	2-44
Review Questions	2-45
Exercise 1	2-46

### **Chapter 3: Adding Constraints and Creating Procedures in the Part Modeler**

Constraining Sketches	3-2
Applying Logical Constraints	3-2
Applying Dimensional Constraints	3-4
Concept of Fully Constrained Sketches	3-7
Fully Constrained	3-7
Over Constrained	3-7
Under Constrained	3-7
Deleting an Over defined Constraint	3-7
Editing a Dimension	3-8

Editing a Constraint	3-9
Creating Base Features	3-9
Creating Extruded Features	3-10
Extrude Tab	3-10
Type Tab	3-12
Creating Base Features by Revolving Sketches	3-14
Dynamically Rotating the View of the Model	3-15
Creating Primitive Features as Base Features	3-16
Creating a Slab	3-16
Creating a Sphere	3-16
Creating a Cone	3-16
Creating a Cylinder	3-17
Creating a Torus	3-17
Modifying the View Orientation	3-18
Display Modes of the Model	3-19
Wireframe	3-19
Wireframe HLD	3-19
Wireframe HLR	3-19
Shaded	3-19
Shaded w/HLD Edges	3-19
Shaded w/HLR Edges	3-19
Perspective View	3-19
Importance of Sketching Planes	3-19
Creating New Planes	3-20
Creating a Plane on a Planar Surface	3-20
Creating a Plane Using the Position - Line Option	3-20
Creating a Plane Tangent to a Surface	3-21
Creating a Plane Normal to a Curve	3-21
Creating a Plane at an Offset from an Existing Plane/Planar Face	3-21
Creating a Plane Parallel to an Existing Plane and Passing Through a Point	3-22
Creating a Plane Tangent to a Non-planar Face and Parallel to a Planar Face	3-22
Creating Boss/Cut/Divide Features	3-23
Creating Boss/Cut Extrude Features	3-23
Creating Boss/Cut Revolve Features	3-24
Advanced Modeling tools	3-25
Creating Fillets	3-25
Creating Chamfers	3-29
Adding a Draft to the Faces of the Model	3-30
Creating a Shell Feature	3-31
Creating a Linear Array	3-31
Creating a Circular Array	3-33
Creating Simple Holes	3-34
Editing Features of the Model	3-37
Tutorial 1	3-38
Tutorial 2	3-44

Self-Evaluation Test	3-48
Review Questions	3-49
Exercise 1	3-50

## **Chapter 4: Creating and Editing Geometries in EdgeCAM**

The Design Mode	4-2
Important Terms	4-3
Construction Plane or CPL	4-3
World Coordinate System	4-3
CPL Coordinate System	4-3
Z Level	4-3
Grid	4-3
Modifying the Grid Settings	4-4
Selecting an Existing Construction Plane	4-4
Working with Standard Views	4-5
Creating Geometric Entities	4-5
Creating Points by Entering Coordinates	4-5
Creating Lines	4-6
Creating Circles	4-8
Creating Arcs	4-9
Creating Cuboids	4-10
Creating Polygons	4-11
Creating Curves	4-12
Creating Spline Curves	4-12
Creating B Spline Curves	4-13
Creating Bezier Spline Curves	4-13
Creating Fitted B Spline Curves	4-13
Generating Intersection Points	4-14
Creating Slot Profiles	4-14
Creating Continuous Entities	4-15
Grouping Entities	4-15
Creating Text Entities	4-16
Editing Geometric Entities	4-17
Projecting Geometric Entities	4-17
Transposing Geometry between the XY and ZX Environments	4-17
Modifying Entity Parameters	4-18
Deleting Entities	4-19
Entity Selection and Referencing Methods	4-19
Reference Input	4-19
Chaining Methods	4-20
Specifying Entities to Snap	4-21
Creating New Construction Planes	4-21
Deleting an Existing CPL	4-22
Using Layers in the Design Mode	4-22
Tutorial 1	4-23

Tutorial 2	4-30
Tutorial 3	4-35
Self-Evaluation Test	4-39
Review Questions	4-40
Exercise 1	4-41
Exercise 2	4-42

## Chapter 5: Importing Solids and Creating Surfaces

Importing Solid Bodies	5-2
Inserting Solid Models	5-2
Changing the View of the Model	5-2
Dynamically Rotating the View of a Model	5-3
Creating Surfaces	5-4
Creating Primitive Surfaces	5-4
Viewing Models in the Wireframe Mode	5-6
Creating Revolution Surfaces	5-7
Creating Ruled Surfaces	5-10
Creating Tabulated Surfaces	5-11
Creating Coons Patch Surfaces	5-11
Creating Flowed Surfaces	5-12
Surface Fillets	5-13
Offset Surfaces	5-15
Trimming Surfaces	5-16
Intersection	5-17
Projecting Curves	5-17
Extending Surfaces	5-18
Creating Corner Blends	5-19
Grouping Surfaces	5-19
Joining Surfaces	5-20
Tutorial 1	5-21
Tutorial 2	5-28
Self-Evaluation Test	5-32
Review Questions	5-33
Exercise 1	5-33
Exercise 2	5-34

## Chapter 6: Milling Cycles

The Manufacture Mode	6-2
Important Terms and Definitions	6-2
Stock/Fixture	6-2
Machine Datum	6-2
Initial CPL	6-2
Clearance Plane	6-3
Retract Plane	6-3
Depth	6-3

Cut Increment	6-3
Level	6-3
Speed	6-3
Plunge Feed	6-3
Feed Rate	6-3
Containment Boundary	6-3
Creating Stocks and Fixtures	6-4
Generating a New Sequence	6-5
Tool Selection	6-6
Milling Cycles	6-6
Generating the Profiling Toolpath	6-7
Generating the Roughing Toolpath	6-9
Generating the Facing Toolpath	6-12
Generating the Drilling Toolpath	6-13
Generating the Text Toolpath	6-15
Generating Toolpaths for an Imported Solid	6-15
Features for Machining	6-16
Identifying Features	6-16
Identifying Features Automatically	6-16
Extracting the Geometry from the Edges	6-18
Generating the Slot Toolpath	6-19
Generating the Flat Land Finishing Toolpath	6-20
Parallel Lace Cycle	6-22
Generating the Rest Finishing Toolpath	6-24
Generating the Pencil Mill Toolpath	6-24
Generating the Constant Cusp Finishing Toolpath	6-26
Simulating the Toolpaths	6-27
Modifying the Toolpath Entities	6-28
Adding Miscellaneous Functions	6-30
Creating the Projection Toolpath	6-30
Project Toolpath	6-30
Generating the Project Boundary Collapse Toolpath	6-32
Generating the Project Flow Curves Toolpath	6-32
Tutorial 1	6-33
Tutorial 2	6-43
Self-Evaluation Test	6-56
Review Questions	6-57
Exercise 1	6-58
Exercise 2	6-59

## Chapter 7: Turning Cycles

Turning Environment	7-2
Creating a Profile in the ZX environment	7-2
Creating Stocks	7-3
Generating Sequences	7-4

Important Tooling Parameters	7-5
Selecting a Predefined Tool	7-6
Defining Tool Parameters	7-7
Importing Solids	7-8
Finding Features	7-8
Turning Cycle	7-9
Creating the Straight Turning Toolpath	7-9
Creating the Rough Turning Toolpath	7-10
Generating the Turning Toolpath for Finishing	7-13
Generating a Toolpath for the Grooves	7-14
Generating the Toolpath for Rough Grooves	7-15
Creating the Finish Groove Toolpath	7-17
Creating the Rough Side Groove Toolpath	7-18
Creating the Finish Side Groove Toolpath	7-20
Tutorial 1	7-21
Tutorial 2	7-26
Self-Evaluation Test	7-34
Review Questions	7-34
Exercise 1	7-35
Exercise 2	7-36

## Chapter 8: Machining Operations and Generating CNC Codes

Machining Operations	8-2
Milling Operations	8-2
Facemill Operation	8-2
Profiling Operation	8-4
Roughing Operation	8-5
Flat Land Finishing Operation	8-6
Slotting Operation	8-8
Parallel Lace Operation	8-9
Rest Finishing Operation	8-10
Chamfer Operation	8-11
Drill Hole Operation	8-12
Editing an Operation	8-13
Turning Operations	8-14
Straight Turning Operation	8-14
Turning Operation	8-15
Grooving Operation	8-16
Threading Operation	8-17
Generating CNC Codes	8-18
Generate CNC Code Dialog box	8-19
Text Editor Window	8-21
Tutorial 1	8-23
Tutorial 2	8-31

Self-Evaluation Test	8-37
Review Questions	8-38
Exercise 1	8-39
Exercise 2	8-40
<b>Student Projects</b>	1
<b>Index</b>	1