

Table of Contents

Dedication	iii
Preface	xxi

Chapter 1: Introduction

Introduction to Autodesk Inventor 2014	1-2
Part Module	1-2
Assembly Module	1-2
Presentation Module	1-3
Drawing Module	1-3
Sheet Metal Module	1-3
Mold Design Module	1-3
Getting Started with Autodesk Inventor	1-3
Quick Access Toolbar	1-7
Ribbon and Tabs	1-7
Sketch Tab	1-8
3D Model Tab	1-8
Sheet Metal Tab	1-9
Assemble Tab	1-9
Place Views Tab	1-9
Presentation Tab	1-10
Tools Tab	1-10
View Tab	1-10
Navigation Bar	1-11
Browser Bar	1-11
Units for Dimensions	1-12
Important Terms and Their Definitions	1-12
Feature-based Modeling	1-12
Parametric Modeling	1-12
Bidirectional Associativity	1-12
Adaptive	1-13
Design Doctor	1-13
Constraints	1-13
Joints	1-15
Consumed Sketch	1-16
Stress Analysis Environment	1-17
Select Other Behavior	1-17
Hotkeys	1-18
Part Module	1-18
Assembly Module	1-19
Drawing Module	1-19
Customizing Hotkeys	1-19
Creating the Sketch	1-21
Marking Menu	1-21

Color Scheme	1-22
Self-Evaluation Test	1-24
Review Questions	1-24

Chapter 2: Drawing Sketches for Solid Models

The Sketching Environment	2-2
The Welcome Dialog Box	2-2
The Open Dialog Box	2-4
Import DWG	2-7
Starting a New File	2-7
Invoking the Sketching Environment	2-8
Introduction to the Sketching Environment	2-9
Setting Up the Sketching Environment	2-9
Modifying the Document Settings of a Sketch	2-9
Sketching Entities	2-11
Positioning Entities by Using Dynamic Input	2-11
Drawing Lines	2-13
Drawing Circles	2-16
Drawing Ellipses	2-17
Drawing Arcs	2-17
Drawing Rectangles	2-19
Drawing Polygons	2-22
Drawing Slots	2-23
Placing Points	2-25
Creating Fillets	2-25
Creating Chamfers	2-26
Drawing Splines	2-28
Deleting Sketched Entities	2-30
Finishing a Sketch	2-31
Understanding the Drawing Display Tools	2-31
Zoom All	2-31
Zoom	2-31
Zoom Window	2-32
Zoom Selected	2-32
Pan	2-32
Orbit	2-33
Constrained Orbit	2-33
Tutorial 1	2-34
Tutorial 2	2-40
Tutorial 3	2-43
Tutorial 4	2-47
Self-Evaluation Test	2-51
Review Questions	2-51
Exercise 1	2-51
Exercise 2	2-53

Exercise 3	2-53
Exercise 4	2-54

Chapter 3: Adding Constraints and Dimensions to Sketches

Adding Geometric Constraints to a Sketch	3-2
Perpendicular Constraint	3-2
Parallel Constraint	3-2
Tangent Constraint	3-3
Coincident Constraint	3-3
Concentric Constraint	3-3
Collinear Constraint	3-4
Horizontal Constraint	3-4
Vertical Constraint	3-4
Equal Constraint	3-5
Fix Constraint	3-5
Symmetric Constraint	3-5
Smooth Constraint	3-6
Viewing the Constraints Applied to a Sketched entity	3-6
Controlling Constraints and Applying them Automatically while Sketching	3-7
Selecting Constraints	3-7
Applying Constraints	3-8
Deleting Geometric Constraints	3-8
Adding Dimensions to Sketches	3-8
Linear Dimensioning	3-9
Aligned Dimensioning	3-11
Angular Dimensioning	3-12
Diameter Dimensioning	3-14
Radius Dimensioning	3-14
Linear Diameter Dimensioning	3-15
Setting the Scale of Sketch	3-16
Creating Driven Dimensions	3-17
Understanding the Concept of Fully-Constrained Sketches	3-18
Measuring Sketched Entities	3-18
Measuring Distances	3-18
Measuring Angles	3-20
Measuring Loops	3-21
Measuring the Area	3-21
Adding Linear Measurements	3-22
Clearing Accumulated Dimensions	3-22
Evaluating Region Properties	3-22
Tutorial 1	3-23
Tutorial 2	3-28
Tutorial 3	3-33
Tutorial 4	3-38
Self-Evaluation Test	3-42
Review Questions	3-43

Exercise 1	3-44
Exercise 2	3-44
Exercise 3	3-45
Exercise 4	3-45
Exercise 5	3-45
Exercise 6	3-46

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities	4-2
Extending Sketched Entities	4-2
Trimming Sketched Entities	4-2
Splitting Sketched Entities	4-3
Offsetting Sketched Entities	4-4
Mirroring Sketched Entities	4-5
Moving Sketched Entities	4-7
Rotating Sketched Entities	4-9
Creating Patterns	4-11
Creating Rectangular Patterns	4-11
Creating Circular Patterns	4-15
Writing Text in the Sketching Environment	4-17
Writing Regular Text	4-17
Writing Text Aligned to a Geometry	4-20
Inserting Images and Documents in Sketches	4-21
Editing Sketched Entities by Dragging	4-22
Tolerances	4-23
Converting the Base Sketch into a Base Feature	4-25
Extruding the Sketch	4-25
Revolving the Sketch	4-29
Direct Manipulation of Features by Using the Mini Toolbar	4-32
Command Options	4-33
Manipulators	4-33
Rotating the View of a Model in 3D Space	4-34
Rotating the View of a Model Using the Orbit	4-34
Changing the View Using the ViewCube	4-35
Navigating the Model	4-38
Controlling the Display of Models	4-39
Setting the Visual Styles	4-39
Setting the Shadow Options	4-41
Setting the Camera Type	4-42
Creating Primitive Shapes	4-43
Tutorial 1	4-45
Tutorial 2	4-49
Tutorial 3	4-52
Tutorial 4	4-56
Self-Evaluation Test	4-59
Review Questions	4-59

Exercise 1	4-61
Exercise 2	4-61
Exercise 3	4-62
Exercise 4	4-62
Exercise 5	4-63
Exercise 6	4-63
Exercise 7	4-64

Chapter 5: Other Sketching and Modeling Options

Need for other Sketching Planes	5-2
Work Features	5-3
Creating Work Planes	5-3
Creating Work Axes	5-13
Creating Work Points	5-17
Other Extrusion Options	5-22
Other Revolution Options	5-28
The Concept of Sketch Sharing	5-30
Tutorial 1	5-31
Tutorial 2	5-36
Tutorial 3	5-41
Self-Evaluation Test	5-45
Review Questions	5-46
Exercise 1	5-47
Exercise 2	5-47
Exercise 3	5-48
Exercise 4	5-49

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes	6-2
Creating Fillets	6-12
Creating Chamfers	6-23
Mirroring Features and Models	6-26
Creating Rectangular Patterns	6-29
Creating Circular Patterns	6-32
Creating Rib Features	6-34
Thickening or Offsetting the Faces of Features	6-38
Creating the Embossed and Engraved Features	6-42
Applying Images on a Feature	6-44
Assigning Different Colors/Styles to a Model	6-45
Assigning Material to the Model	6-46
Modifying the Properties of an Existing Material	6-46
Tutorial 1	6-48
Tutorial 2	6-54
Tutorial 3	6-60
Tutorial 4	6-67

Tutorial 5	6-71
Self-Evaluation Test	6-78
Review Questions	6-78
Exercise 1	6-80
Exercise 2	6-81
Exercise 3	6-82

Chapter 7: Editing Features and Adding Automatic Dimensions to Sketches

Concept of Editing Features	7-2
Editing Features of a Model	7-2
Updating Edited Features	7-4
Editing Features Dynamically by Using 3D Grips	7-4
Editing the Sketches of Features	7-6
Redefining the Sketching Plane of a Sketched Feature	7-8
Suppressing Features	7-9
Unsuppressing the Suppressed Features	7-10
Moving the Faces of a Solid	7-10
Free Move Method	7-10
Direction and Distance Method	7-11
Points and Plane Method	7-11
Deleting Features	7-12
Copying and Pasting Features	7-13
Manipulating Features By EOP	7-15
Adding Automatic Dimensions to Sketches	7-16
Projecting Entities in the Sketching Environment	7-17
Projecting Edges or Faces	7-18
Projecting Cutting Edges	7-18
Project to 3D Sketch	7-19
Tutorial 1	7-20
Tutorial 2	7-27
Tutorial 3	7-31
Self-Evaluation Test	7-38
Review Questions	7-38
Exercise 1	7-39
Exercise 2	7-40
Exercise 3	7-41
Exercise 4	7-42
Exercise 5	7-43

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools	8-2
Creating Sweep Features	8-2
Creating Lofted Features	8-10
Creating Coil Features	8-20

Enhanced

Creating Threads	8-24
Creating Shell Features	8-26
Applying Drafts	8-29
Creating Split Features	8-32
Trimming Surfaces	8-35
Extending Surfaces	8-36
Deleting Faces	8-37
Replacing Faces with Surfaces	8-39
Creating Planar Boundary Patches	8-41
Stitching Surfaces	8-43
Working with the Sculpt Tool	8-44
Working with the Bend Part Tool	8-45
Reordering the Features	8-48
Using the Sketch Doctor	8-49
Using the Design Doctor	8-50
Tutorial 1	8-51
Tutorial 2	8-55
Tutorial 3	8-58
Tutorial 4	8-60
Tutorial 5	8-63
Self-Evaluation Test	8-65
Review Questions	8-66
Exercise 1	8-67
Exercise 2	8-68

Chapter 9: Assembly Modeling-I

Assembly Modeling	9-2
Types of Assemblies	9-2
Top-down Assemblies	9-2
Bottom-up Assemblies	9-3
Creating Top-down Assemblies	9-3
Creating Components in the Assembly Module	9-4
Creating Bottom-Up Assemblies	9-7
Placing Components in the Assembly File	9-7
Assembling Components by Using the Constrain Tool	9-8
Assembly Tab	9-8
Motion Tab	9-17
Transitional Tab	9-18
Constraint Set Tab	9-19
Specifying the Limits for Constraining	9-19
Assembling Parts by Using the Assemble Tool	9-20
Using ALT+Drag to Apply Assembly Constraints	9-22
Applying Joints to the Assembly	9-22
Joint Tab	9-22
Limits Tab	9-27

Showing and Hiding Relationships	9-28
Show Relationship	9-28
Hide Relationship	9-28
Show Sick Relationship	9-28
Moving Individual Components	9-29
Rotating Individual Components in 3D Space	9-29
Tutorial 1	9-29
Tutorial 2	9-45
Tutorial 3	9-53
Self-Evaluation Test	9-63
Review Questions	9-64
Exercise 1	9-65

Chapter 10: Assembly Modeling-II

Editing Assembly Constraints	10-2
Editing Components	10-3
Editing Components in the Assembly File	10-3
Editing Components by Opening their Part Files	10-5
Creating Subassemblies	10-5
Creating a Subassembly Using the Bottom-up Design Approach	10-6
Creating a Subassembly Using the Top-down Design Approach	10-6
Checking Degrees of Freedom of a Component	10-6
Creating the Pattern of Components in an Assembly	10-7
Component	10-7
Associative Tab	10-8
Rectangular Tab	10-9
Circular Tab	10-9
Replacing a Component from the Assembly File with another Component	10-10
Replacing a Single Instance of the Selected Component	10-10
Replacing all Instances of the Selected Component	10-11
Mirroring Subassemblies or Components of an Assembly	10-12
Copying Subassemblies or Components of an Assembly	10-15
Deleting Components	10-16
Editing the Pattern of Components	10-16
Making a Pattern Instance Independent	10-17
Deleting Assembly Constraints	10-18
Creating Assembly Section Views in the Assembly File	10-18
Analyzing Assemblies for Interference	10-19
Creating Design View Representations	10-20
Design View Representation Area	10-21
Positional Representation Area	10-22
Level of Detail Representation	10-22
Simulating the Motion of Components of an	
Assembly by Driving Assembly Constraints	10-22
Creating Positional Representations	10-25
Viewing the Bill of Material of the Current Assembly	10-26
Working with Assembly Features	10-28

Tutorial 1	10-28
Tutorial 2	10-31
Tutorial 3	10-32
Self-Evaluation Test	10-38
Review Questions	10-39
Exercise 1	10-40

Chapter 11: Working with Drawing Views-I

The Drawing Module	11-2
Types of Views	11-3
Generating Drawing Views	11-5
Generating the Base View	11-5
Generating Projected Views	11-10
Generating Auxiliary Views	11-12
Generating Section Views	11-13
Generating Detail Views	11-15
Generating Broken Views	11-17
Generating Break Out Views	11-19
Generating Overlay Views	11-21
Generating Slice Views	11-23
Drafting Drawing Views	11-24
Editing Drawing Views	11-24
Deleting Drawing Views	11-25
Moving Drawing Views	11-27
Copying Drawing Views	11-27
Rotating Drawing Views	11-27
Changing the Orientation of Drawing Views	11-29
Assigning Different Hatch Patterns to Components in Assembly Section Views	11-29
Editing the Default Hatch Style of the Sectioned Objects	11-32
Excluding Components from Assembly Section Views	11-33
Tutorial 1	11-35
Tutorial 2	11-40
Self-Evaluation Test	11-45
Review Questions	11-46
Exercise 1	11-47

Chapter 12: Working with Drawing Views-II

Modifying Drawing Standards	12-2
Inserting Additional Sheets into Drawing	12-3
Activating a Drawing Sheet	12-3
Displaying Dimensions in Drawing Views	12-3
Retrieving Parametric Dimensions in Drawing Views	12-4
Adding Reference Dimensions	12-5
Modifying the Model Dimensions	12-5
Editing Drawing Sheets	12-5

Creating Dimension Styles	12-7
Applying Dimension Styles	12-8
Modifying a Dimension and its Appearance Using the Shortcut Menu	12-8
Adding the Parts List	12-9
Source Area	12-9
BOM Settings and Properties Area	12-10
Table Wrapping Area	12-10
Editing the Parts List	12-11
Column Chooser	12-12
Group Settings	12-12
Filter Settings	12-13
Sort	12-13
Export	12-13
Table Layout	12-13
Renummer Item	12-13
Save Item Overrides to BOM	12-14
Member Selection	12-14
Adding/Removing Custom Parts	12-14
Shortcut Menu Options	12-14
Setting the Standard for the Parts List	12-15
Adding Balloons to Assembly Drawing Views	12-15
Adding Balloons to Selected Components	12-16
Adding Automatic Balloons	12-16
Adding Text to a Drawing Sheet	12-18
Adding Multiline Text without a Leader	12-19
Adding Multiline Text with Leader	12-20
Tutorial 1	12-21
Tutorial 2	12-26
Tutorial 3	12-31
Self-Evaluation Test	12-36
Review Questions	12-36
Exercise 1	12-37

Chapter 13: Presentation Module

The Presentation Module	13-2
Creating the Presentation View	13-3
Assembly Area	13-3
Explosion Method Area	13-4
Defining Units for Presentation Files	13-6
Tweaking Components in the Presentation View	13-6
Create Tweak Area	13-6
Transformations Area	13-8
Animating an Assembly	13-9
Rotating the Presentation View Precisely	13-15
Tutorial 1	13-16
Tutorial 2	13-23

Self-Evaluation Test	13-29
Review Questions	13-30
Exercise 1	13-32

Chapter 14: Working with Special Design Tools

Adaptive Parts	14-2
Defining Parameters	14-2
Working with iParts	14-6
Types of iPart Factories	14-7
Creating iPart Factories	14-7
Procedure to Create an iPart	14-13
Inserting an iPart into an Assembly	14-14
Changing the iParts in the Assembly File	14-17
Creating 3D Sketches	14-17
Line	14-18
Spline	14-18
Bend	14-19
Include Geometry	14-19
Intersection Curve	14-19
Helical Curve	14-20
Tutorial 1	14-20
Tutorial 2	14-25
Tutorial 3	14-30
Tutorial 4	14-33
Tutorial 5	14-37
Self-Evaluation Test	14-44
Review Questions	14-45
Exercise 1	14-46

Chapter 15: Working with Sheet Metal Components

The Sheet Metal Module	15-2
Setting Sheet Metal Component Parameters	15-4
Setting the Sheet Metal Rule	15-4
Setting the Material Style	15-12
Setting the Unfolding Rule	15-12
Creating Sheet Metal Components	15-14
Folding Sheet Metal Components	15-18
Adding Flanges to Sheet Metal Components	15-20
Creating Cuts in Sheet Metal Components	15-25
Creating Seams at the Corners of Sheet Metal Components	15-26
Bending the Faces of a Sheet Metal Component	15-30
Rounding the Corners of Sheet Metal Components	15-33
Chamfering the Corners of Sheet Metal Components	15-34
Punching 3D Shapes into Sheet Metal Components	15-35
Creating Hems	15-38

Creating Contour Flanges	15-40
Creating the Flat Patterns of Sheet Metal Components	15-42
Adding or Removing Material from the Flat Pattern	15-43
Tutorial 1	15-44
Tutorial 2	15-50
Self-Evaluation Test	15-56
Review Questions	15-57
Exercise 1	15-58

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies	16-2
Main Types of Welds in Autodesk Inventor	16-3
Cosmetic Welds	16-3
Fillet Welds	16-4
Groove Welds	16-4
Adding Welds to Assemblies	16-5
Assembling the Components of Weldment Assemblies	16-5
Preparing Assemblies for Weldments	16-6
Adding Welds	16-6
Creating Fillet Welds	16-6
Creating Cosmetic Welds	16-8
Creating Groove Welds	16-10
Creating Symbols	16-11
Creating Report	16-11
Tutorial 1	16-12
Tutorial 2	16-17
Self-Evaluation Test	16-21
Review Questions	16-22
Exercise 1	16-23

Chapter 17: Miscellaneous Tools

Copying the Sketches	17-2
Scaling the Sketches	17-3
Finding the Center of Gravity	17-3
Extracting the iFeature	17-4
Inserting the iFeature	17-6
Creating iMates	17-7
Applying iMates in the Assembly Environment	17-9
Interactively Place with iMates	17-9
Automatically Generate iMates on Place	17-9
Viewing the iProperties	17-9
Creating User-Defined Drawing Sheets	17-11
Importing AutoCAD Blocks into Inventor	17-18
Tutorial 1	17-21
Tutorial 2	17-26

Self-Evaluation Test	17-29
Review Questions	17-30
Exercise 1	17-32

Chapter 18: Introduction to Plastic Mold Design

Introduction to Plastic Mold Design	18-2
Invoking the Mold Design Environment	18-2
Methods of Designing Core and Cavity	18-2
Importing Plastic Part in Mold Environment	18-3
Adding Core and Cavity	18-4
Adjusting Orientation and Position of the Part	18-5
Adjusting Orientation of the Part	18-5
Adjusting Position of the Part	18-6
Selecting Material	18-8
Commonly Used Material	18-8
Specific Material	18-8
Details	18-9
Report	18-10
Creating Core and Cavity for the Part	18-11
Adjusting Orientation	18-11
Specifying Gate Location	18-11
Settings for the Process	18-15
Analyzing Part for Filling	18-17
Specifying Shrinkage Allowance	18-17
Defining Workpiece	18-19
Creating Patching Surface	18-21
Creating Planar Patches	18-22
Creating Runoff Surface	18-22
Generating Core and Cavity	18-23
Creating Pattern of the Mold	18-26
Creating a Rectangular Pattern	18-26
Creating a Circular Pattern	18-26
Creating a Variable Pattern	18-27
Creating Runner of the Mold	18-28
Creating Runner Sketch	18-28
Creating Runner	18-30
Creating Gates for the Molds	18-31
Placement	18-33
Copy of all Pockets	18-33
Adding Cold Wells	18-33
Adding Mold Base to the Assembly	18-33
Standard Area	18-34
Placement Area	18-35
Layout Information Area	18-36
Adding Sprue Bushing	18-36
Adding Cooling Channel	18-37

Generating Drawing Views	18-38
Tutorial 1	18-39
Self-Evaluation Test	18-59
Review Questions	18-59
Exercise 1	18-60

Chapter 19: Introduction to Stress Analysis

Introduction to FEA	19-2
Types of Engineering Analysis	19-3
Structural Analysis	19-3
Thermal Analysis	19-4
Fluid Flow Analysis	19-5
Electromagnetic Field Analysis	19-5
Coupled Field Analysis	19-5
General Procedure to Conduct Finite Element Analysis	19-5
FEA Through Software	19-6
Important Terms and Definition	19-7
Strength	19-7
Load	19-7
Stress	19-7
Strain	19-8
Elastic Limit	19-8
Ultimate Strength	19-8
Factor of Safety	19-9
Lateral Strain	19-9
Poisson' Ratio	19-9
Bulk Modulus	19-9
Stress Concentration	19-9
Bending	19-9
Bending Stress	19-9
Creep	19-9
Degrees of Freedom	19-10
Stress Analysis in Autodesk Inventor 2014	19-10
Creating Simulation	19-11
Using the Guide Tool	19-14
Applying Stress Analysis Settings	19-14
Stress Analysis Browser Bar	19-15
Assigning Material	19-16
Assign Material	19-16
Applying Constraints	19-18
Fixed	19-18
Pin	19-19
Frictionless	19-20

Applying Loads	19-20
Force	19-20
Pressure	19-22
Bearing Load	19-23
Moment	19-23
Gravity	19-24
Remote Force	19-24
Body	19-25
Meshing the Component	19-26
Mesh View	19-26
Mesh Setting	19-26
Local Mesh Control	19-28
Convergence Setting	19-29
Solution Phase of Analysis	19-29
Postprocessing the Solutions	19-30
Generating Report	19-30
Animating the Result	19-32
Tutorial 1	19-32
Tutorial 2	19-38
Tutorial 3	19-42
Self-Evaluation Test	19-53
Review Questions	19-54
Exercise 1	19-55
Exercise 2	19-56
Index	I-1

Evaluation Copy. Do not reproduce. For information visit www.cadcim.com